

# WD100

## Flomatic $\frac{3}{4}$ -1" PVB Check Tool

### Works On:

Model:

$\frac{3}{4}$ " – 1" PVB

Use:

Removal of check valve

Tool Includes:

Check socket.

$\frac{3}{8}$ " drive socket wrench  
not included.



The check valve is threaded into the body and sealed by an o-ring.

Place the tool on a  $\frac{3}{8}$ " drive socket wrench.

Place tool over the check valve and loosen counter-clockwise.

